

PRODUCT DISCONTINUATION NOTICE

PDN NO.: IKL2012-001

IXYS Product Type:	Type	Recommended replacement
	SLMD121H04	SLMD121H04L
	SLMD121H06	SLMD121H06L
	SLMD121H08	SLMD121H08L
	SLMD121H09	SLMD121H09L
	SLMD121H10	SLMD121H10L
	SLMD480H12	SLMD480H12L
	SLMD600H10	SLMD600H10L
	SLMD960H12	SLMD960H12L

Reason: Switch from epoxy coating to lamination version due to higher reliability performance

Last time order date: Apr. 30th, 2012

Last time delivery date: May. 31st, 2012

Internal Reference: IKPO_2012_001

In case of any question, please contact

Initiator	Title/Function	Date	e-mail
Bill	MP	Mar. 30th, 2012	b.lee@ixys.net

IXYS Korea Ltd.
 R&DB Center Suite#420, 906-5, Iui-Dong,
 Yeongtong-Gu, Suwon, Gyeonggi-Do, Korea(443-766)
 Phone: +82-31-888-5232
 Fax: +82-31-888-5233

Customer response:

(Please fill in and return by e-mail, fax, or mail within 2 weeks)

<input type="checkbox"/> for further questions/information please comment	Company: _____ Name & Position: _____ Phone/Fax No.: _____
--	--

Comments: _____

